

FIG.1



FIG.2




FIG.3




FIG.4




FIG.5A




FIG.5B




FIG.6




FIG.7




FIG. 8A




FIG. 8B




FIG.9A

STEP-DOWN SWITCHING




FIG.9B




FIG.10A




FIG.10B




FIG. 11





FIG.12A



MEASUREMENT PATTERN

FIG.12B




FIG. 13

